

Package ‘PDM’

October 12, 2022

Type Package

Title Photogrammetric Distances Measurer

Version 0.1

Date 2016-08-20

Author J.F. Palomeque-Gonzalez and M. San-Juan

Maintainer J.F. Palomeque-Gonzalez <jfpalomeque.gonzalez@gmail.com>

Depends R (>= 3.1.0), jpeg

Description Measures real distances in pictures. With PDM() function, you can choose one '*.jpg' file, select the measure in mm of scale, starting and finishing point in the graphical scale, the name of the measure, and starting and finishing point of the measures. After, ask the user for a new measure.

License GPL

LazyData TRUE

NeedsCompilation no

Repository CRAN

Date/Publication 2016-08-21 18:33:03

R topics documented:

PDM	1
Index	3

PDM	<i>Photogrammetric Distances Measurer</i>
-----	---

Description

This package can measures real distances in pictures. With PDM() function, you can choose one .jpg file, select the measure in mm of scale, starting and finishing point in the graphical scale, the name of the measure, and starting and finishing point of the measures. After, ask the user for a new measure.

Usage

PDM()

Details

Photogrammetric Distances Measurer

Value

Measures data frame

Note

NULL

Author(s)

J.F. Palomeque-Gonzalez and M. San-Juan

References

NULL

See Also

NULL

Examples

```
##---- Should be DIRECTLY executable !! ----  
##-- ==> Define data, use random,  
##--or do help(data=index) for the standard data sets.  
  
## The function is currently defined as
```

Index

PDM, 1